





U.S. 1 800 394-9900 Int'l +1 818 837-8100

info@futuregraphicsllc.com  
www.futuregraphicsllc.com



QTY		CONTENT	
<b>1</b>		<b>FG Compatible Replacement Chip</b>	
Reorder No.: T640CHIPHY		High Yield: 21K	
For use in: Lexmark® T640/642/644		I.D. 	
NOT AN OEM PRODUCT		Product color may vary	



**STEP 1:**

Remove OEM chip

**STEP 2:**

To install new chip peel liner backing from chip and insert as shown

**STEP 3:**

Test Cartridge

<p><b>CAUTION:</b> Before post testing cartridge, insure that the cartridge is full of toner. Adding toner after print testing can cause the printer to stop printing and display an "Invalid Refill" message. Printing with a partially filled toner cartridge can cause the printer to not indicate 100% toner remaining on the Menu Page at install.</p>	<p><b>USE COMPATIBLE REPLACEMENT CHIP ONLY FOR:</b></p> <ul style="list-style-type: none"> <li>• Replacing lost or damaged chips for non "Cartridge Return" style cartridges.</li> <li>• Upgrading non "Cartridge Return" style cartridge functionality.</li> </ul>
<p>Future Graphics is a distributor of compatible replacement parts and products for imaging equipment. This product is not a genuine OEM product and no affiliation or sponsorship is to be inferred between Future Graphics and any OEM. Trademarks and brand names are the properties of their respective owners and are used for descriptive purposes only.</p> <p style="text-align: right;">ZCLBLT640HY 5/06</p>	